#8-335 P.119



N. T. S.

SET L & TAG, PLS 5691, IN WALK; TANGENT TIE; CHISELED "T". SET L & TAG, PLS 5691, IN WALK; TANGENT TIE; CHISELED "T".

VERDUGO AVE.

FIND. SPK. & WASHER DN. 0.04';
RE-PUNCHED SPK. PER TIES.

FIND L & T

FIND L

CORNER RECORD Document Number _ BURBANK County of Los Angeles, California VERDUGO AVE.& CORDOVA ST. - C/L - MONUMENT PRESERVATION Brief Legal Description **CORNER TYPE COORDINATES (Optional)** N. Govt. Corner Control E._ __ NAD27 🗆 NAD83 Zone _ Meander Property NAD83 Epoch __ Elev. Other Rancho NAVD88 NGVD29 Vert. Datum: Date of Survey May 18, 2003 Imperial Meas. Units: Metric Rebuilt Found & tagged Established Reestablished 2 Left as found Corner -Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: see plat: distances measured horizontal; A description of the physical condition of the monument as found and as set or reset: see plat: SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance May 30, 2003 with the Land Surveyors' Act on ___ 5691 P.L.S. or R.C.E. No. Signed

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received ______and examined and filed _____

Signed ______ P.L.S. or R.C.E. No. _____

Title:

County Surveyor's Comment _____